


An Explosion Diagram Of Parts List ATV-4000



ATV-4000c

NO	Name of parts	Qty	NO	Name of parts	Qty	NO	Name of parts	Qty
1	Clutch knob	1	25	Tie bar	2	49	Handle switch	1set
2	Headed inner hexagon screw	3	26	Motor support rack	1	50	C-ring	2
3	Spring washer	3	27	Headed inner hexagon screw	4			
4	Clutch rack	1	28	Spring washer	4			
5	C-ring	1	29	Connecting shaft	1			
6	Rotator	1	30	Axle	1			
7	Axle	1	31	Braking plate	1			
8	Copper washer	1	32	Brake set	1			
9	1 st pinion	1	33	Wedge shape piece B	1			
10	1 st carrier	1set	34	Wedge shape piece A	1			
11	Copper washer	2	35	C-ring	2			
12	2 nd carrier	1set	36	Braking clutch base	1			
13	Plain washer	1	37	Motor	1			
14	Anti-leak seal	2	38	Base frame	1			
15	1 st , 2 nd & 3 rd ring gear	1	39	4 way roller fairlead	1set			
16	P 1 st shaft	1	40	Wire rope with hook	1set			
17	Steel wire shield ring	1	41	Copper washer	2			
18	Copper washer	1	42	Electromagnetic switch set	1set			
19	Clutch gear	1	43	TA-0108 pulley block	1set			
20	Pressed spring	1	44	Manual	1set			
21	Body support rack	1	45	Handsaver strap	1			
22	Drum bushing	2	46	Wire protector	4			
23	3 rd carrier	1set	47	Screw	1set			
24	Grub inner screw	1	48	Cable tie	8			